SEPA

POTENTIAL HAZARDOUS WASTE SITE PRELIMINARY ASSESSMENT PART 1 - SITE INFORMATION AND ASSESSMENT

di state de ste munes.
Ms D000773564

		I TOTAL	an white fell	HEDRIT L	(13)	2000773564
THE NAME AND LOCATION						
OT SIT TAXAS CARD IN TERRET OF TRANSPORT OF SITE		02 37	T AOUTE NO O	TO SECURIOR STATE		
Illinois Central Gulf-Louisvi	lle, MS	Can	ele Stree	t and Highw	av 15	
03 CITY					ay 15	
Louisville, Mississippi		MS	39339			0/COUNTY 00 CC
OS COOPERATES LATITUDE	Out of			- ZiiSton		
TO DIRECTIONS TO SITE . Surray was record and	L _ J L					
Site is just to the west of H	fahuar 15 ar		.b. C	L . 6 C 1		282
Louisville, MS.	-6	iu to	the sout	n or cagle	street	ın
M. RESPONSIBLE PARTIES						
01 OWNER A Second		02 8174	-			
Midsouth Railroad						
Marv		da STATE	4 2 4	IM TO THE OWNER OF		
Jackson	ţ					
OF OPERATOR of Majors and officers from manage				1.0017 333	7,500	
Gulf and Mississippi Railroad	- 1					
SE CITY		161.71	11 1 200			
Columbus		MS				
13 Tries Of Company Company			33701	1601 329-	6620	
CA PRIVATE C B. PEDERAL:			C C STATE	(10 cores	~ · · · ·	
CIF onesCorporate	(Agency resig				- L -UN	CPA.
			U & UNEQ.			
WORTH GAY FEAT	3 5. 00000000000000000000000000000000000	O WASIE	MIT COME IN CO.	DATE RECEIVED:		TC NOME
IV. COMPLETE PROCESS OF STREET SEA SECTION						
OI ON SITE NAMED TON	PA GB. BAC	CONTRAC	TOR 0.0	STATE CO	07-	
OI ON SITE NAMED TON	PA GB. BAC	OMTRAC AL G	TOR O	STATE GO	OTHER C	ONTRACTOR
GT ON SITE NAME OF THE O	PA G B. SPAC CCAL HEALTH OFFICE ACTOR NAME(S):		TOR 0 0	STATE CO	ОТН Е Я СС	DATRACTOR
OT ON SITE NOME CONTROL OF THE STATUS CONTRO	PA G B. SPAC CCAL HEALTH OFFICE ACTOR NAME(S):		F. officer	STATE CO.	0TH46F1 CC	DATRACTOR
OT ON SITE PROPERTION OT YES DATE OF MO CONTRA OT SITE STATUS COURS ON OT A ACTIVE OF SMACTIME OF C. UNEQUIDMEN	PA G B. SPAC OCAL HEALTH OFFICE ACTOR MANE(S): OS YEARS OF GREAT	6. G	r. other	764	-	DATRACTOR
OT ON SITE PROPERTION OT YES DATE OF MO CONTRA OT SITE STATUS COURS ON OT A ACTIVE OF SMACTIME OF C. UNEQUIDMEN	PA G B. SPAC OCAL HEALTH OFFICE ACTOR MANE(S): OS YEARS OF GREAT	6. G	r. other	764	-	DATRACTOR
G1 ON SITE NEWFOLTON Q YES OATE Q NO CONTRA CE SITE STATUS COME ON CA ACTIVE Q S. SHACTIVE Q C. UNSQUOMN C4 DESCRIPTION OF SASSTANCES POSSELY PROSENT, SHOWIN, C	PA G B. SPAC CCAL HEALTH OPPICE ACTOR NAME(S): 03 YEARS OF CHEALTH	AL C	F. OTHER	- 0	-	DATRACTOR
G1 ON SITE NEWFOLTON Q YES OATE Q NO CONTRA CE SITE STATUS COME ON CA ACTIVE Q S. SHACTIVE Q C. UNSQUOMN C4 DESCRIPTION OF SASSTANCES POSSELY PROSENT, SHOWIN, C	PA G B. SPAC CCAL HEALTH OPPICE ACTOR NAME(S): 03 YEARS OF CHEALTH	AL C	F. OTHER	- 0	-	DHITRACTOR
OF SHE STATUS COMPANY OF SUSTAINCES POSSELY PROSECUTION OF SUSTAINCES POSS	CAL HEALTH OFFICE ACTOR NAMES: OS YEARS OF CHART MALASSO heavy meta	AL C	F. OTHER	- 0	-	DATRACTOR
OF SHE STATUS COMPANY OF SUSTAINCES POSSELY PROSECUTION OF SUSTAINCES POSS	CAL HEALTH OFFICE ACTOR NAMES: OS YEARS OF CHARTS THE ALLESS TH	AL C	F. OTHER	- 0	-	DATRACTOR
GI ON STREET COMPANY TO STREET CONTROL OF CO	PA OB PAC COLHEATH OFFICE ACTOR NAMES: DISTRIBUTION TALLESS heavy meta	ls, b	F. OTHER	- 0	-	DATRACTOR
GI ON STREET COMPANY TO STREET CONTROL OF CO	PA OB PAC COLHEATH OFFICE ACTOR NAMES: DISTRIBUTION TALLESS heavy meta	ls, b	F. OTHER	- 0	-	DATRACTOR
GI ON STREET COMPANY TO STREET CONTROL OF CO	PA OB PAC COLHEATH OFFICE ACTOR NAMES: DISTRIBUTION TALLESS heavy meta	ls, b	F. OTHER	- 0	-	DITRACTOR
Tilinois Central Guif-Louisville, MS Cagle Street and Highway 15 Cagle S						
OF SHE STATUS COMPANY OF SHEET AND CONTROL OF SHEET AND CONTROL OF SHEET AND	ACTOR MANER: OS VENE OF CHAIR heavy meta	ls, b	attery ac	id a	-	DATRACTOR
OF CHARTY ASSESSMENT	ACTOR HAMES: AC	ls, b	attery ac	id .	-	DATRACTOR
OF CHART AND THE CONTROL OF THE CONTROL OF CONTROL OF CHART AND THE CONTROL OF CONTROL OF CHART AND THE CONTROL OF CHART	ACTOR HANDS: AC	ls, b	attery ac	id .	-	DATRACTOR
OF CHESTATUS COMPANY OF THE STATUS CONTROL OF CONTROL OF CHESTANCES POSSELY PROBLEM AND CONTROL OF CHESTANCES PROBLEM AND CONTRO	ACTOR HANDS: AC	ls, b	attery ac	id .		
OF CHESTATUS CONTROL OF CONTROL OF CONTROL OF CONTROL OF CHESTANCES POSSELY PROBLEM AND OTHER POSSELS FOR CONTROL OF CHESTANCES POSSELY PROBLEM AND OTHER POSSELS FOR CONTROL OF CHESTANCES POSSELS FOR CONTROL OF CONTROL O	ACTOR HANDS: AC	ls, b	attery ac	ild	PRODUCTION OF THE PRODUCTION O	TELEPHONE HUMBER
OF CHARTY ASSESSMENT OF CHARTY OF CHARTY ASSESSMENT OF CHARTY ASSESSMENT OF CHARTY ASSESSMENT OF CHARTY OF CHARTY ASSESSMENT OF CHARTY	heavy meta acron manage: asymmeta heavy meta around wat	ls, b	attery ac	ild	PRODUCTION OF THE PRODUCTION O	TELEPHONE HUMBER
OF CHARTE AND	heavy meta ground wat	ls, b	attery ac	lution Cont	rol (6	TELES-COM MUMBER (OL) 961-5.71
OF CHARTY ASSESSMENT OF CHARTY OF CHARTY ASSESSMENT OF CHARTY ASSESSMENT OF CHARTY ASSESSMENT OF CHARTY ASSESSMENT OF CHARTY OF CHARTY ASSESSMENT OF CHARTY	heavy meta acron manage: asymmeta heavy meta around wat	ls, b	attery ac	id lution Cont	rol (6	101, 961-5.71

SEPA

POTENTIAL HAZAROOUS WASTE SITE PRELIMINARY ASSESSMENT

	PERCATION
OI STATE	D00077356-

PART 3 - DESCRIPTION OF H	AZARDOUS CONDITIONS AND INCIDENT	M5	D00077356→
II. HAZAROUS CONDITIONS AND INCIDENTS			
21 X A GROUNDWATER CONTAMINATION 23 POPULATION POTENTIALLY AFFECTED:	02 C OBSERVED (DATE) 04 NARRATIVE DESCRIPTION	I POTENTAL	- ALEGED
possible, but highly unlikely			
01 X8 SURFACE WATER CONTAMINATION 03 POPULATION POTENTIALLY AFFECTED	02 - COSSERVED (OATE	= POTENTIAL	= ALEGED
Possible- Oil and grease releases above NPDES	levels documented		
01 T C CONTAMBATION OF AR 03 POPULATION POTENTIALLY AFFECTED None	02 CESSTVEDIDATE.	S POTENTIAL	- ALEGED
01 = 0 FIRE-ESPLOSIVE CONDITIONS 03 POPULATION POTENTIALLY AFFECTED:	04 C OBSERVED (DATE	C POTENTIAL	= ALEGED
None			
01 I E DIRECT CONTACT 03 POPULATION POTENTIALLY APPECTED:	02 C CORRETVED (CATE.	S POTENTIAL	I ALEGED
None			
01 X/F CONTAMBATION OF SOIL 03 AREA POTENTIALLY APPECTED:	04 NAMATIVE DESCRIPTION	C POTENTIAL	= ALEGEO
Possible			
01 = Q. OFFICIAL WATER CONTAMINATION 03 POPULATION POTENTIALLY APPECTED:	04 NATURATIVE DESCRIPTION	O POTENTIAL	CALEGED
None			
01 CAN WORKER ESTERMALLY ASSECTED:	OZ C CREENED (DATE:) OA MARKATINE CRECTE/TION	C POTENTAL	S ALEGED
Possible			
01 C : POPULATION EXPOSURE/SULEY 03 POPULATION POTENTIALLY APPECTED:	02 C CONSERVED (DATE: 1	O POTENTAL	C ALLEGED
None			

House 3

PRELIMINARY ASSESSMENT MSD000773564

H 21 x 12 = 2

A) SITE DESCRIPTION

The Illinois Central Gulf (ICG) railroad yard is located just west of Highway 15 on the southern edge of the City of Louisville, Winshn Co. Mississippi. Louisville is about 80 miles northeast of Jackson, Mississippi. (12)

The site is a servicing point for diesel locomotives. Though it is listed as an ICG facility on the CERCLIS list, it is actually run by Gulf and Mississippi (G & M) Railroad, whose offices are in Columbus, Mississippi. (1, 2)

B) DESCRIPTIONS OF HAZARDOUS CONDITIONS

The facility services long haul diesel locomotives. According to Mississippi Bureau of Pollution Control's Industrial Wastewater files, the facility does have a permitted discharge of oil and grease. It is unknown how old the facility is. Fuel and lubricants are the most likely contaminants. Also possibly present is PCB, which was used for a time in the electrical system of diesel locomotives. Other possible contaminants are battery wastes, heavy metals (from batteries) and acids (also from batteries). (2, 4, 5)

Around 1979, an oil spillage collection facility was installed to contain oil and fuel spills during servicing.

C) NATURE OF HAZARDOUS MATERIALS

Though it is unclear whether there are any chemical contaminants onsite, described here are some hazardous properties of possible contaminants.

Gasoline (fuel) is a skin and eye irritant. Because it defats the skin, dermatitis may result from prolonged or repeated contact. Also, gasoline vapors depress the central nervous system.

Polchlorinated biphenyls (PCBs) may have been used in the trains vast electrical systems. PCBs are a class B2 carcinogen. Prolonged skin contact may cause chloracne. Also, extended exposure may cause liver damage and stillbirth to children whose mothers were exposed during pregnancy.

Cadmium is also a carcinogen. It is a respiratory tract irritant, causes pulmonary edema and emphysema. (7, 8)

D) RCRA STATUS

The site does not appear under "Illinois Central Gulf" or "Gulf and Mississippi" on the Hazardous Waste Data Management System (HWDMS) list.

G & M Railroad did, however, submit a Form OMB #2000-0098 request as a hazardous waste transporter. The EPA identification number issued was MSD98102"436. This request is not site specific to the Louisville facility.

E) ROUTES OF CONTAMINATION

A windshield survey of the site was not performed, so there isn't a clear picture of routes of contamination and human exposure. The state NPDES file, however, says that the effluent leaves the site via an unnamed stream. This stream discharges into Hughes Creek, which, in turn, discharges into Tallahaga Creek.

Surface water contamination would be the most apparent route of offsite contaminant migration. Oil, grease and diesel fuel discharges would be evident in the stream. Any PCB or metals contamination would be transported offsite by sediments carried by runoff. These would concentrate in stream sediments rather than in surface water. Though MPDES permit violations are documented, they are infrequent.

The potential for impact to groundwater would be minimal due to the nature of possible contaminants. Oil, grease, diesel fuel, PCBs and metals all tend to adhere to soil particles and not migrate through the soil matrix.

The only possible impact to air quality would be the volatilization of diesel fuel, particularly after a spill. However, no spills are documented. Oil, grease, PCBs and metals all tend not to threaten air quality.

Oil, grease, and diesel fuel are all skin irritants. However, the threat of direct contact to PCBs and metals is greater because the effects are more severe and long-lasting. (5, 7, 8, 12)

F) POSSIBLE AFFECTED POPULATION AND RESOURCES

A house count is not attempted in this preliminary assessment. However, a three mile radius around the site would encompass the entire City of Louisville, which has a population of about 7,800. Including residents who live outside the city limits but inside the three mile radius, the total population inside the three mile radius is certainly higher. (3)

The city has five public wells within a single field, located about 1/4 mile from the site boundary. All of these wells are 300 - 400 feet deep and draw from the Lower Wilcox aquifer. There are no rural water association wells within a three mile radius. (3, 6)

Lake Tiak O'Khata, a local resort area, is about 1 1/2 miles from the site. It would not appear to be affected by surface water discharges from the site.

G) GEOLOGY

The site is located on an outcrop of the Middle Wilcox formation. This formation is about 250 feet thick below the site and consists of marls, clays, and sands. The Meridian-Upper Wilcox formation, a major aquifer in the state, crops out southwest of the site in a northwest-southeast band. The Lower Wilcox aquifer, another significant water-bearing zone, crops out northeast of the site, also in a northwest-southeast band. It is about 150 feet thick below the site. Recharge is from rainfall on the outcrops. The formation dips to the southwest, and groundwater flow is generally in this direction. However, it may be influenced locally by pumpage. All of Louisville's public wells are in this zone.

Below the Wilcox is the Midway group. The Porter's Creek formation of this group is a 600 feet thick clay confining bed and hydraulically isolates the Lower Wilcox Aquifer from lower aquifers. Also in the Midway group is the Clayton formation, a 30 feet thick formation that is not an aquifer.

Beneath the Wilcox group is the Selma group. The Selma, as a whole, is 800-1000 feet thick. In it are the Ripley formation and the Coffee Sand, which are smaller aquifers. Upper chalk formations of the Selma overlie the Ripley. Between the Ripley and the Coffee are the Demopolis chalk and the lower transitional clays of the Ripley. Below the Coffee are the Mooresville chalk and the Arcola Limestone. The Ripley and the Coffee are used as aquifers only well north of the site area.

Below the Selma are the Eutaw and McShan formations which together form the Eutaw-McShan Aquifer system. The top of the Eutaw is about 2000 feet below ground level. The entire system is about 500 feet thick.

Below the Eutaw-McShan is the Tuscaloosa group. The Gordo and the Coker formations comprise the Tuscaloosa, and both contain significant water-bearing zones. Below the Tuscaloosa is the Lower Cretaceous series, and below that is the Paleozoic series. (9, 10, 11)

H) RECOMMENDATIONS

There was not enough information gathered during the preparation of this preliminary assessment to assign a "No Further Action" rating to the site. It is not believed that there is any significant environmental problems at this site. However, due to the large target population and the proximity to the city wells, a closer examination of this site needs to be taken in order to confirm this. Therefore, the State rates Illinois Central Gulf/Louisville site as a "Low" priority site for a site investigation.

References

- 1) Conversation with Bob Strong of Illinois Central, phone log, 12/21/87.
- 2) Conversation with Peter Terrell of Gulf and Mississippi Railroad, phone log, 12/28/87.
- 3) Conversation with Tommy Kirkpatrick of Louisville Department of Public Works, phone log, 12/29/87.
- 4) Record of conversation with Richard Ball of MSBPC, 3/16/88.
- 5) Copy of NPDES Discharge Permit for ICG/Louisville.
- 6) U.S.G.S. Well log printout of Winston County, Mississippi.
- 7) Sittig, Marshall, <u>Handbook of Toxic and Hazardous Chemicals and Carinogens</u>, second edition, Noyes Publications, Park Ridge, New Jersey.
- 8) Superfund Public Health Evaluation Manual, EPA 540/186/060, 1986.
- 9) Gandl, L. A., <u>Characterization of Aquifers Designated as Potential Drinking Water Sources in Mississippi</u>, U.S.G.S. Water Resources Investigation Open-File Report 81-550, 1982.
- 10) Mellen, Frederic Frances, Mississippi State Geological Survey Bulletin 38, Winston County Mineral Resources, 1939.
- 11) Taylor, R. E. and Thomson, F. H., <u>Water For Industrial Development in Kemper, Leaks, Neshoba, Noxubee, and Winston Counties, Mississippi.</u>
 U.S.G.S. Water Resources Division and Mississippi Research and Development Center, 1972.
- 12) U.S.G.S. Topographic Maps, 7.5 Minute Series; Betheden, Boon, Louisville South and Louisville North Quadrangles.

1	D SUBSIDIARIES	TELECON NOTE
	Reference No. 6	_
CONTROL NO. F4-8809-02	DATE: April 4, 1989	TIME: 1440
DISTRIBUTION:		
File Illinois Central Gulf		
BETWEEN: Joyce Kirkpatrick	OF: City Clerk Louisville, MS	PHONE: (601) 773-9201
AND: Steve Cash, NUS Corpo	Step D. 2	al
DISCUSSION:		
with 650 persons. Both Georg In the city limits, there are the Elementary Jr. High and High are engaged in agriculture. Ti	gia Pacific and TRW are the next largest e hree public# schools and one private sch School. Outside the city limits, resident: he major crops grown in the area are con eside in single-family residences. There	tal Machine Works as the largest employer mployers and employees 574 persons each. nool. The public schools are the Louisville seither commute into Louisville to work or n, cotton, soybeans and the raising of dairy is one nearby recreation area, Lake Tia O
ACTION ITEMS:		

Approved RNI RNI

FINAL REPORT SCREENING SITE INSPECTION, PHASE II ILLINOIS CENTRAL GULF RAILROAD LOUISVILLE, WINSTON COUNTY, MISSISSIPPI EPA ID #: MSD000773564

Prepared Under TDD No. F4-8809-02 CONTRACT NO. 68-01-7346

Revision 0

FOR THE

WASTE MANAGEMENT DIVISION
U.S. ENVIRONMENTAL PROTECTION AGENCY

DECEMBER 7, 1989

NUS CORPORATION SUPERFUND DIVISION

Prepared By

Reviewed By

Approved By

Stephen Cash

Project Manager

Phil Blackwell

Assistant Regional

Project Manager

Murray Warner, P.E.

Regional Project Manager

NOTICE

The information in this document has been funded wholly by the United States Environmental Protection Agency (EPA) under Contract Number 68-01-7346 and is considered proprietary to the EPA.

This information is not to be released to third parties without the expressed or written consent of the EPA.

TABLE OF CONTENTS

24C	tion No.	Page No
EXE	CUTIVE SUMMARY	ES-
1.0	INTRODUCTION	
1.1		
1.2	Scope of Work	;
2.0	SITE CHARACTERIZATION	_
2.1	Site Background and History	3
2.2	Site Description	3
	2.2.1 Site Features	3
	2.2.2 Waste Characteristics	6
3.0	REGIONAL POPULATIONS AND ENVIRONMENTS	7
3.1	Population and Land Use	7
	3.1.1 Demography 3.1.2 Land Use	7
3.2	Surface Water	7
J. L	3.2.1 Climatology	7
	3.2.2 Overland Drainage	7
	3.2.3 Potentially Affected Water Bodies	8
3.3	Regional Aquifer Characteristics	8
	3.3.1 Aquifer Description	8
	3.3.2 Aquifer Use	9
3.4	Summary of Potentially Affected Populations and Environments	10
4.0	FIELD INVESTIGATION	11
4.1	Sample Collection	11
	4.1.1 Sample Collection Methodology	11
	4.1.2 Duplicate Samples	11
	4.1.3 Description of Samples and Sample Locations 4.2 Sample Analysis	11
	4.2.1 Analytical Support and Methodology	15
	4.2.2 Analytical Data Quality	15
	4.2.3 Presentation of Analytical Results	15 16
5.0	SUMMARY	
- 10		24
	RENCES	26
APPE	NDIX A Site Inspection Report	
APPE	NDIX B Map of 4-Mile Site Radius	

APPENDIX C Analytical Results

Number		Page No.
Table 1	Sample Codes, Descriptions, and Field Measurements	13
Table 2	Inorganic Analyses - Surface and Subsurface Soil Samples	17
Table 3	Inorganic Analyses - Sediment Soil Samples	18
Table 4	Organic Analyses - Surface and Subsurface Soil Samples	
Table 5	Organic Analyses Sadiment College and Sabsatriace Son Samples	19
	Organic Analyses - Sediment Soil Samples	21
Table 6	Inorganic Analyses - Groundwater Samples	22

FIGURES

Number		Page No.
Figure 1	Site Location Map	4
Figure 2	Site Layout Map	5
Figure 3	Sample Location Map	12

EXECUTIVE SUMMARY

The Illinois Central Gulf Railroad facility is located in Louisville, Winston County, Mississippi. The current owner of the property is the South Rail Corporation, a subsidiary of the Mid South Corporation. The site is located in a railroad yard, which has been in existence for 75 to 100 years. In 1978, a fueling and service center was constructed where locomotives are supplied with diesel fuel and serviced. In addition, the diesel locomotives are occasionally washed.

When the fueling and service center was constructed, an oil collection system was installed to collect oil spilled during the servicing of locomotives. This oil collection system is a series of in-ground grates that collects surface runoff in an underground oil and water separator. The oil remains in the underground separator to be pumped out at a later time, while the water is discharged into a nearby ditch via an underground pipe. The facility has a NPDES permit to discharge into the ditch.

At the time of construction of the fueling and service station, several areas of oil-contaminated soil were removed. The contaminants that were most likely present in the soil are diesel fuel and lubricants, of which heavy metals and numerous hazardous organic materials could be constituents, and solvents used for degreasing of locomotive parts. The American Creosote Company was formerly located adjacent to the Illinois Central Gulf facility and produced creosote at the plant. EPA conducted a remedial action at American Creosote to remove contaminants.

The facility is located in the Mississippi Embayment of the Atlantic Coastal Plain Physiographic Province in central Mississippi. The aquifer of concern, the lower Wilcox aquifer, is the main water-producing aquifer within the 4-mile site radius. Thick beds of clay separate the middle Wilcox aquifer from the lower Wilcox aquifer, forming a confining layer.

The city of Louisville has five municipal wells, which are located one-half mile to the south of the Illinois Central Gulf facility. These wells range in depth from 260 to 400 feet below land surface and draw water from the lower Wilcox aquifer. Within a 4-mile radius of the site, residents obtain water from the Louisville Municipal system or one of four rural water associations.

The rural water associations obtain groundwater from wells located outside the 4-mile radius study area. All residents inside the city of Louisville are connected to the municipal system, and there is no

known use of private wells. Residents outside the city limits have access to either the Louisville system or one of the four rural water associations, and use of private wells for potable water is limited.

Analytical results for soils show the solvent tetrachloroethane and its degradation products, and toluene in onsite soils but not in background samples. Migration of solvents off site does not appear to be occurring. Solvents were not detected in soils of the drainage ditch located offsite. The presence of many polynuclear aromatic hydrocarbons (PNAs) were detected, in addition to the presumptive evidence of petroleum products in soil samples. Those compounds cannot be attributed to site practices. The American Creosote Company, formerly located adjacent to the site, produced creosote. Many of the PNAs found in the soil samples are constituents of creosote. Railroad ties located in the rail yard are also a probable source of creosote. PNAs were detected in the background sediment soil sample, located upgradient of the site, indicating the site is being influenced by offsite conditions.

Inorganic analysis showed lead to be above background values at two onsite locations, including the drainage ditch. Lead does not appear to be migrating offsite since lead was not found in downgradient soil of the drainage ditch. Analytical results of a municipal water sample did not show elevated levels of organic or inorganic constituents.

The only pathways of concern for this facility are the air and onsite exposure pathways. The presence of contaminated surface soils was confirmed by this investigation. However, the population within 1 mile of the site is only 411. PNAs are relatively insoluble in water, migration into the groundwater unlikely and the aquifer of concern is protected by thick beds of clay. Therefore, FIT 4 recommends that no further remedial action be planned for Illinois Central Gulf Railroad.

1.0 INTRODUCTION

The NUS Corporation Region 4 Field Investigation Team (FIT) was tasked by the U.S. Environmental Protection Agency (EPA), Waste Management Division to conduct a screening site inspection (SSI) at the Illinois Central Gulf Railroad site in Winston County, Mississippi. The investigation was performed under the authority of the Comprehensive Environmental Response Compensation and Liability Act of 1980 (CERCLA) and the Superfund Amendments and Reauthorization Act of 1986 (SARA). The task was performed to satisfy the requirements stated in Technical Directive Document (TDD) number F4-8809-02. The field investigation was conducted during the period of October 10-12, 1988.

1.1 OBJECTIVES

The objectives of this investigation were to determine the nature of contaminants present at the site and to determine if a release of these substances has occurred or may occur. Further, this investigation sought to determine the possible pathways by which contamination could migrate from the site and the populations and environments it would potentially affect. Through these objectives, a recommendation was made regarding future activities at the site.

1.2 SCOPE OF WORK

The objectives were achieved through the completion of a number of specific tasks. These activities were to:

- obtain and review relevant background materials;
- obtain aerial photographs and maps of site;
- obtain information on local water systems;
- evaluate populations and environments potentially affected via the groundwater, surface water, and onsite exposure pathways;

- determine location and distance to nearest potable well;
- develop a scaled facility map;
- collect 11 environmental samples of soil and groundwater; and
- complete a Site Inspection Report, provided as Appendix A in this report.

2.0 SITE CHARACTERIZATION


2.1 SITE BACKGROUND AND HISTORY

The Illinois Central Gulf Railroad facility is located west of Highway 15 on the southern edge of the city of Louisville, Winston County, Mississippi. The site location is shown in Figure 1. The facility is operated as a fueling and service center for diesel locomotives. The locomotives are provided with diesel fuel, mechanically serviced and are occasionally washed. The rail yard in which the fueling center is located has been in existence for 75 to 100 years. Before 1978, the site contained a turntable track system, where locomotives could be switched to different tracks. In 1978, the fueling station was constructed, along with an oil collection system to contain oil and fuel spilled during servicing. At that time, the turntable track system was removed along with surface soils contaminated with oils (Ref. 1, pp. 2-4). The facility currently has a NPDES permit to discharge water collected in the oil/water separator into a nearby ditch (Ref. 2). The facility has changed ownership several times in recent years. Illinois Central Gulf Railroad was sold to Gulf and Mississippi Railroad in 1985, and in 1987 the South Rail Corporation, the current owner, purchased the property. South Rail is a subsidiary of the Mid South Corporation (Ref. 1, p. 3).

2.2 SITE DESCRIPTION

2.2.1 Site Features

The Illinois Central Gulf Railroad facility is located in a rail yard in the city of Louisville, Mississippi. The site layout is shown in Figure 2. The facility lies along the main railroad tracks, which run in a north-south direction. The main tracks consist of about eight separate lines. These main railroad tracks mark the western boundary of the fueling and service facility and Highway 15 roughly forms the boundary to the east. The site contains a service area with a rail line where locomotives can be refueled. The service area also contains a concrete pit so the locomotives can be serviced from below. Diesel fuel is contained in a 23,000-gallon fuel tank located to the west of the service area and is pumped through an underground pipe to the service area. A 6000-gallon lube oil tank is also located there, and both are diked by a concrete wall. Adjacent to the south end of the service area is a steel tank containing sand. The sand is loaded onto the locomotives to be used for rail traction. Next to the sand tank is a square concrete pad containing two manholes. This pad covers the




BASE MAP IS A PORTION OF THE U.S.G.S. 7.5 MINUTE QUADRANGLE LOUISVILLE NORTH 1972, LOUISVILLE SOUTH 1972, MISSISSIPPI.

SITE LOCATION MAP
ILLINOIS CENTRAL GULF RAILROAD
LOUISVILLE, WINSTON COUNTY, MISSISSIPPI

FIGURE 1





SITE LAYOUT MAP ILLINOIS CENTRAL GULF RAILROAD LOUISVILLE, WINSTON COUNTY, MISSISSIPPI

FIGURE 2



underground oil and water separator and the sampling and metering station for the NPDES-permitted discharge. An underground pipe leads from the oil and water separator, travels south and east under the railroad tracks, and empties into a ditch via a concrete culvert. This ditch lies between railroad tracks and Highway 15 and flows southward. Highway 15 and the railroad tracks cross to the south, and the drainage ditch passes under the highway via a culvert. The ditch drains into Hughes Creek one-half mile to the south. The site is not enclosed by a fence and access could be obtained. The American Creosote Company was formerly located directly across the main tracks to the west of the site. American Creosote is no longer an active facility (Ref. 3).

2.2.2 Waste Characteristics

In 1978, when the oil and water collection system was installed, surface soils contaminated with oil were removed to a depth of approximately 8 inches. The area of soil removal was west of the oil water separator around the railroad track. In addition, soil from a drainage path leading east from the service area to the ditch was removed, as well as soil from the ditch, to a point past the current NPDES discharge point (Ref. 4).

File material does not indicate any storage or disposal of hazardous materials at the site. The most likely contaminants would be diesel fuel and lubricants spilled during servicing. Oil collected in the underground oil/water separator is pumped out and disposed of off site at two-year time intervals (Ref. 1, pp. 5-6). Other contaminants that possibly could be present would include PCBs, which were used for a period of time in the electrical systems of diesel locomotives, and lead from batteries used in the locomotives. Industrial solvents used for cleaning could possibly be present as well (Ref. 5). Remedial action was taken by EPA at the American Creosote Company when the facility was still in operation. Reportedly, Hughes Creek was polluted by contaminants from American Cresote (Ref. 3). Due to American Creosote's proximity to Illinois Gulf Control Railroad, it is possible this site could have been influenced by conditions at American Creosote.

3.0 REGIONAL POPULATIONS AND ENVIRONMENTS

3.1 POPULATION AND LAND USE

3.1.1 <u>Demography</u>

Within a 4-mile radius of the Illinois Central Gulf Railroad facility, both the city of Louisville and rural areas are present. Manufacturing is the town's main industry, with Total Machine Works, Georgia Pacific and TRW being Louisville's largest employers. Within the 4-mile radius of the site there are four schools, Louisville Elementary, Junior High, and High School, as well as a private school (Ref. 6). Louisville Junior High is the closest school at 0.75 mile in distance from the site (Appendix B). The total population, obtained from 1980 census data, within the 4-mile radius is 7273 residents. Within a 1-mile radius of the site, there are 441 residents (Ref. 7).

3.1.2 Land Use

The area surrounding the Illinois Central Gulf Railroad facility, outside the city limits of Louisville is mostly rural containing single-family residences and small farms. Those persons who do not commute into the city of Louisville to work in manufacturing are engaged in agriculture. Dairy cattle are raised and the crops grown in the area are corn, cotton, soybeans. Lake Tiak-O'Khata is the only recreational area within the 4-mile radius and is located approximately 1.5 miles to the southwest of the site. Lake Tiak-O'Khata is privately owned and is used as a vacation and conference center (Ref. 6). Lake Tiak-O'Khata is not under the influence of the site via any potential migration routes.

3.2 SURFACE WATER

3.2.1 Climatology

Winston County has a temperate climate; the summers are generally warm and humid, and winters are moderately cold. Annual precipitation averages 51 inches. Annual free water evaporation from shallow lakes and ponds averages 43 inches, making the net precipitation approximately 8 inches (Ref. 8).

3.2.2 Overland Drainage

Surface water runoff from the site would drain into a series of storm grates around the fueling and service facility and be collected in the underground oil and water separator system. The runoff water would then travel through an underground pipe to an unnamed ditch to the west of the facility and be discharged (Ref. 1, pp. 3-4). This ditch travels south along Highway 15 for approximately one-half mile before joining Hughes Creek. Hughes Creek also flows south for approximately 7.5 miles before it joins Tallahaga Creek. The slope of the intervening terrain from the point of the service center to surface water is 1 percent (Appendix B).

3.2.3 <u>Potentially Affected Water Bodies</u>

Both the Hughes and Tallahaga Creeks could be potentially affected by contaminants carried by surface water runoff from the Illinois Central Gulf Railroad facility. Hughes Creek is not used for recreation due to pollution in the past from a nearby creosote plant; however, Tallahaga Creek is used for recreational fishing. The U.S. Soil Conservation Service has plans to channelize this portion of the Tallahaga Creek, thereby eliminating this fishing area. One irrigation system obtains its water from Hughes Creek, approximately 8 miles south of Louisville. Within 15 stream miles from the facility, there are no surface water intakes used for public drinking water supplies. There are no known sensitive environments or endangered species in the study area (Ref. 15, Appendix 8).

3.3 REGIONAL AQUIFER CHARACTERISTICS

3.3.1 Aquifer Description

The site is located in the Mississippi Embayment of the Atlantic Coastal Plain Physiographic Province in central Mississippi. About 10% of the recharge to groundwater is through direct precipitation. Additional recharge occurs through the infiltration of surface water into the aquifers (Ref. 9, p. 269). Louisville lies within the Pearl River drainage basin.

The underlying formations, of Tertiary age, are, in descending order: the Bashi Marl Member, Tuscahoma Formation, Nanafalia Formation, and Fearn Springs Member of the Wilcox Group; and the Naheola Formation, Porters Creek Clay, and Clayton Formation of the Midway Group. The Porters Creek Clay (between 470 and 810 feet thick) and the Clayton Formation (between 20 and 50 feet thick) act as confining units, along with the underlying Cretaceous age Owl Creek Formation, that

restrict the migration of water from the overlying Tertiary aquifers into the Cretaceous formations below (Ref. 10, p. 3).

The Bashi Marl Member and Tuscahoma Formation form the Middle Wilcox aquifer. The Bashi Marl is a glauconitic sand containing large calcareous, fossiliferous concretions. The irregular sand beds of the Tuscahoma Formation are the water-bearing units of the Middle Wilcox aquifer. Small to moderate yields are obtained from a few community and domestic wells (Ref. 12, p. 33). The aquifer is up to 310 feet thick in the immediate vicinity of the site (Ref. 11, pp. 42, 46). Thick beds of clay separate the Middle Wilcox aquifer from the Lower Wilcox aquifer (Ref. 12, p. 66).

The Lower Wilcox aquifer is comprised of the Nanafalia, Fearn Springs, and Naheola formations. The Nanafalia is a fossiliferous marl with basal sand beds. The Fearn Springs Member is composed of irregular beds of fine to coarse sand, lignitic clay and bauxite, and the Naheola Formation is composed of fine to coarse micaceous sand, kaolin and bauxitic clay. Moderate to large yields are obtained from wells in this aquifer (Ref. 11, p. 8). In Winston County the aquifer is 285 feet thick (Ref. 11., p. 41). Transmissivity values of the Lower Wilcox aquifer in the Louisville area are greater than 10,000 ft.²/day; about 1 million gallons per day (gpd) are pumped from the aquifer here (Ref. 12, p. 68). Several public supply wells, ranging from 204 to 447 feet deep, tap the Lower Wilcox aquifer near the site (Ref. 11, p. 42, 46).

The Porters Creek Clay confining unit is a dark gray clay, slightly glauconitic with micaceous sand lenses. Along with the greenish-gray, sandy clay and marl of the Clayton Formation and the blue, glauconitic sandy clay of the Owl Creek Formation, the Porters Creek Clay forms a confining layer. This layer can be from 600 to 2000 feet thick in the Louisville area (Ref. 5; Ref. 11, p. 33).

3.3.2 Aquifer Use

The city of Louisville and the areas immediately adjacent to the city limits are served by the Louisville municipal water system. The system obtains its water from five wells which range in depth from 260 feet to 400 feet below land surface. The closest municipal well is located approximately one-quarter mile to the south of the Illinois Central Gulf facility. In addition to the Louisville Municipal Water System, four rural water associations supply water to residents inside the 4-mile radius study area. These water associations are the Flower Ridge, Calvary Water, Highpoint and Bond water system and all obtain groundwater from wells outside the 4-mile radius area (Ref. 1). All residents inside the city of Louisville are connected to the municipal system, and there is no known use of private wells (Ref. 13).

Residents outside the city limits have access to either the Louisville system or one of the four rural water associations, and use of private wells for potable water is very limited. The Louisville system supplies water to approximately 7800 residents (Refs. 13, 14).

3.4 SUMMARY OF POTENTIALLY AFFECTED POPULATIONS AND ENVIRONMENTS

There are two pathways of concern for the facility: the air and onsite exposure pathways. Potential for site-related contaminant release to the surface water pathway is not a concern due to the lack of potentially affected populations and environments. The groundwater pathway is also not a concern due to confining beds of clay overlying the aquifer from which municipal water is drawn.

The air and onsite exposure pathways are of concern due to the presence of uncontained, contaminated soils. Potentially affected targets within a 4-mile radius include students, employees and residents. The population of residents within 4-miles of the site is estimated at 7273. Targets for onsite exposure include 441 residents located within a 1-mile radius of the site (Ref. 7).

4.0 FIELD INVESTIGATION

4.1 SAMPLE COLLECTION

4.1.1 <u>Sample Collection Methodology</u>


All sample collection, sample preservation, and chain-of-custody procedures used during this investigation were in accordance with the standard operating procedures as specified in Sections 3 and 4 of the Engineering Support Branch Standard Operating Procedures and Quality Assurance Manual; United States Environmental Protection Agency, Region IV, Environmental Services Division, April 1, 1986.

4.1.2 <u>Duplicate Samples</u>

Duplicate samples were offered to Mr. Jerry Weeks, the representative of Mid South Corporation. Mr. Weeks declined the duplicate samples. Receipt for sample forms are on file at FIT 4.

4.1.3 <u>Description of Samples and Sample Locations</u>

The sampling investigation consisted of the collection of three surface soil samples, three subsurface soil samples, four sediment samples, and one municipal well sample. Samples were collected on October 11 and 12, 1988. Sample locations are shown in Figure 3 and sample codes and descriptions are given in Table 1. Background surface and subsurface soil samples (IG-SS-01 and IG-S8-04) were taken from one location in a large field near the intersection of Cagle Street and Railroad Avenue. These soils were collected off site and were in an area that appeared to not have been influenced by site conditions. Surface and subsurface soil samples (IG-SS-02 and IG-SB-05) were collected adjacent to the fueling station where locomotives are serviced. An additional set of paired surface and subsurface soil samples (IG-SS-03 and IG-SB-06) were collected adjacent and to the east of the fueling and service station, north of the sand tank. These samples were collected to establish the presence or absence of contaminants.



SAMPLE LOCATION MAP
ILLINOIS CENTRAL GULF RAILROAD
LOUISVILLE, WINSTON COUNTY, MISSISSIPPI

FIGURE 3



SAMPLE CODES, DESCRIPTIONS, AND FIELD MEASUREMENTS SURFACE SOIL, SUBSURFACE SOIL AND SEDIMENT SAMPLES ILLINOIS CENTRAL GULF RAILROAD LOUISVILLE, WINSTON COUNTY, MISSISSIPPI

Sample Code (IG)	Description/Location	Date (1988)	Time
SS-01	A surface soil sample collected from a field off site at the intersection of Cagle Street and Railroad Avenue. This sample was collected to establish background conditions.	10/11	1055
SS-02	A surface soil sample collected at the locomotive fueling station.	10/11	1615
SS-03	A surface soil sample collected from the east side of the fueling station, north of the sand tank.	10/11	1715
SB-04	A subsurface soil sample collected 3 feet below land surface (bls) at the same location as IG-SS-01. This sample was collected to establish background conditions.	10/11	11/10
SB-05	A subsurface soil sample collected at the same location as IG-SS-02. The sample was collected 3 feet below land surface (bls).	10/11	1630
SB-06	A subsurface soil sample collected at the same location as IG-SS-02. The sample was taken 3 feet below land surface (bls).	10/11	1730
SD-07	A sediment soil sample collected from the drainage ditch, 350 feet upgradient of the NPDES discharge. This sample was taken to establish background conditions.	10/11	1420
SD-08	A sediment soil sample collected from a drainage ditch where the NPDES discharge occurs. The ditch drains to the south between Highway 15 and railroad tracks. The sample was collected 5 feet downgradient from the discharge point of the oil and water separator.	10/11	1320
SD-0 9	A sediment soil sample collected from the drainage ditch downgradient of the discharge point. The sample was collected at a location before the ditch passes under Highway 15 via a culvert.	10/11	1320
SD-10	A sediment soil sample collected from the ditch, downgradient of the discharge point. The sample was collected midway between the point of discharge and the intersection of the ditch with Highway 15.	10/11	1500

IG - Illinois Central Gulf Railroad

SS - Surface Soil Sample

SB - Subsurface Soil Sample

SD - Sediment Sample

PW - Potable Well Sample

TABLE 1, continued

SAMPLE CODES, DESCRIPTIONS, AND FIELD MEASUREMENTS GROUNDWATER SAMPLES ILLINOIS CENTRAL GULF RAILROAD LOUISVILLE, WINSTON COUNTY, MISSISSIPPI

Sample Code (IG)	Description/Location	Date (1988)	Time	рН	Temp. (°C)	Conductivity (umhos/cm)
PW-11	A groundwater sample collected from well No. 4 at the city of Louisville's municipal wellfield, located one-quarter mile south of the site. The depth of the well is 260 feet below land surface.	10/12	1000	6.0	19	140

IG - Illinois Central Gulf Railroad

SS - Surface Soil Sample SB - Subsurface Soil Sample

SD - Sediment Sample PW - Potable Well Sample One sediment sample (IG-SD-07) was collected from a drainage ditch where wastewater from the oil and water separator is discharged. The sample was collected 75 feet upgradient of the discharge point to establish background conditions in the ditch. Three sediment samples were collected in the drainage ditch downgradient of the discharge point. One sediment sample (IG-SD-08) was collected five feet downgradient of the discharge point. The second sediment sample (IG-SD-10) was collected between IG-SD-08 and where the ditch passes under Highway 15. The third sediment sample (IG-SD-09) was collected immediately before the ditch passes under Highway 15. All three of these sediments were collected to establish the presence or absence of contaminants.

One public well was sampled during this investigation. The well is located in the city of Louisville wellfield, approximately one-quarter mile south of the site. The well was sampled in order to establish the presence or absence of contaminants in the groundwater.

4.2 SAMPLE ANALYSIS

4.2.1 Analytical Support and Methodology

All samples collected were analyzed under the Contract Laboratory Program (CLP) and analyzed for all parameters listed in the Target Compound List (TCL). Organic analysis of soil and water samples was performed by Environmental Monitoring and Services (EMSI) of Camarillo, California. Inorganic analysis of soil and water was performed by Cambridge Analytical Associates of Boston Maine.

All laboratory analyses and laboratory quality assurance procedures used during this investigation were in accordance with standard procedures and protocols as specified in the <u>Analytical Support Branch Operations and Quality Assurance Manual</u>, United States Environmental Protection Agency, Region IV, Environmental Services Division, revised June 1, 1985; or as specified by the existing United States Environmental Protection Agency standard procedures and protocols for the contract analytical laboratory program.

4.2.2 Analytical Data Quality

All analytical data were subjected to a quality assurance review as described in the EPA Environmental Services Division laboratory data guidelines. In the tables, some of the concentrations of the organic and inorganic parameters have been flagged with a "J". This indicates that the qualitative analysis was acceptable, but the quantitative value has been estimated. A few other compounds are flagged with an "N" indicating that they were detected based on the presumptive

evidence of their presence. This means that the compound was tentatively identified, and its detection cannot be used as positive identification to its presence. The complete analytical data sheets are presented in Appendix C.

4.2.3 <u>Presentation of Analytical Results</u>

Analytical results for surface and subsurface soils show the presence of numerous purgeable, extractable and unidentified compounds, as well as the presumptive evidence for petroleum products. The inorganic analytical results are presented in Table 2 through 5, and the organic analytical results are presented in Table 6.

One set of paired surface and subsurface soil samples (IG-SS-02, IG-SB-05) located adjacent to the fueling and service area, showed the presence of solvents. The chlorinated solvent tetrachloroethane, its degradation products, and toluene were not detected in background soil samples but were found in onsite soil samples. The highest value found for tetrachloroethane was an estimated value of 1900 ug/kg and the highest value for toluene was an estimated 560 ug/kg at the surface soil location IG-SS-02. The other set of paired surface and subsurface soil samples located on site did not show the presence of the chlorinated solvents, although toluene was found at a value of 170 ug/kg in the subsurface soil. Tetrachloroethene and toluene are commonly used degreasers and it is probable that these solvents are used to degrease locomotives when they undergo servicing.

Analysis of sediment soils taken from the drainage ditch did not indicate solvents are migrating off site. Neither tetrachloroethene or its degradation products were found in any of the sediment soils taken from the ditch. Toluene was found to be present in only the background sample. Xylenes were found at the NPDES discharge point, but not in any other downgradient sediment samples. Toluene was not detected in any other downgradient sediment sample.

All surface, subsurface and sediment samples showed the presence of many extractable compounds. Polynuclear aromatic hydrocarbons (PNAs), the presumptive evidence of petroleum products, and numerous unidentified compounds were found. Most of the extractable compounds are associated with coal-tar creosote, which is used to preserved railroad ties.

The mobility of polynuclear aromatic hydrocarbons in the environment is low and migration is unlikely. PAHs are relatively insoluble in water and are strongly adsorbed onto suspended particulate matter, especially particulates high in organic content. It is likely these compounds accumulate in sediments and that that adsorption to sediments is the dominant aquatic means of transport (Ref. 16).

TABLE 2

SUMMARY OF INORGANIC ANALYTICAL RESULTS SURFACE AND SUBSURFACE SOIL SAMPLES ILLINOIS CENTRAL GULF RAILROAD LOUISVILLE, MISSISSIPPI

	Back	ground	Onsite					
PARAMETERS (mg/kg)	IG-55-01	IG-SB-04	IG-55-02	IG-58-05	IG-55-03	IG-58-06		
ALUMINUM	5000	9400	3700	4600	2000	13,000		
ANTIMONY	-		-	31	2.7J	-		
ARSENIC	2.4J	•	213	3J	4.5)	3.3J		
BARIUM	23	17	91	57	28	34		
CALCIUM	1100	820	660	790	930	170		
CHROMIUM	5 4)	3.3)	331	581	8.5J	31,		
COBALT	•	9.4	-	12		11		
COPPER	7.6	3.2	74	22	17	8.9		
RON	90001	21,000J	43,0001	27,0001	88001	31,000J		
LEAD	33	-	170	24	51	8.7		
MAGNESIUM	260	350	270	180	420	310		
MANGANESE	88	33	78	63	160	25		
NICKEL	•	5.9	9.8					
POTASSIUM	260	290	580	370	170	290		
SELENIUM	-	+	2.1	-		-		
SODIUM	-	-	140	-		+		
/ANADIUM	15J	4.6J	391	38,	32,1	461		
INC	33	14	50	34	100	26		
YANIDE	•		-	-	1.33			

Material analyzed for but not detected above minimum quantitation limit

J Estimated value

TABLE 3

SUMMARY OF INORGANIC ANALYTICAL RESULTS SEDIMENT SOIL SAMPLES ILLINOIS CENTRAL GULF RAILROAD LOUISVILLE, MISSISSIPPI

	Background	Drainage Ditch				
PARAMETERS (mg/kg)	IG-SD-07	IG-SD-08	IG-SD-09	IG-5D-10		
ALUMINUM	17,000	4900	20,000	8000		
ANTIMONY	,	5.3J	4.6J	6.11		
ARSENIC	171	9.6J	9.71	7.41		
BARIUM	42	82	82	43		
CALCIU M	1200	2100	3500	840		
CHROMIUM	18J	16J	273	123		
COBALT		•		-		
COPPER	12	230	150	130		
RON	18,000J	22.0 00 J	21,000J	16,0001		
LEAD	30	1300	150	230		
MAGNESIUM	810	530	1300	480		
MANGANESE	37	240	78	60		
NICKEL	-	-	13	13		
POTASSIUM	700	280	750	420		
SELENIUM		-	-	-		
ODIUM	. 1	730	•	-		
/ANADIUM	31J	231	301	18J		
INC	46	210	160	76		
YANIDE	<u> </u>	_		_		

Material analyzed for but not detected above minimum quantitation limit

J Estimated value

SUMMARY OF ORGANIC ANALYTICAL RESULTS SURFACE AND SUBSURFACE SOIL SAMPLES ILLINOIS CENTRAL GULF RAILROAD LOUISVILLE, MISSISSIPPI

	Back	ground	Onsite				
PARAMETERS (ug/kg)	IG-SS-01	IG-SB-04	IG-SS-02	IG-SB-05	IG-55-03	IG-SB-06	
PURGEABLE COMPOUNDS							
1,1-DICHLOROETHENE	-		28,1	3.1		 	
1,1-DICHLOROETHANE			-	3,1	-	<u> </u>	
1,1,1-TRICHLOROETHANE			1500յ	190	<u> </u>	 	
TETRACHLOROETHENE	-	-	1900J	200	-	 	
TOLUENE			5601	<u> </u>		170	
TOTAL XYLENES				<u> </u>	 		
EXTRACTABLE COMPOUNDS						 	
NAPHTHALENE		-	1500)	210)	180)	2201	
2-METHYLNAPHTHALENE			2100J	3001	310)	5401	
ACENAPHTHYLENE	-		1		1001		
DIBENZOFURAN			600J	1 .	170)	3001	
PHENANTHRENE	841		1600J	390)	7001	580)	
ANTHRACENE	·				75)		
LUORANTHENE	1901	† ·	670)	240)	810)	991	
YRENE	150J	· ·	-	2601	7001	2101	
ENZO(A)ANTHRACENE	97)			130,	3401	1107	
HRYSENE	140J		530)	1601	490)	130	

- Material analyzed for but not detected above minimum quantitation limit

N Presumptive evidence of presence of material

J Estimated value

SUMMARY OF ORGANIC ANALYTICAL RESULTS SURFACE AND SUBSURFACE SOIL SAMPLES ILLINOIS CENTRAL GULF RAILROAD LOUISVILLE, MISSISSIPPI

	Background		Onsite			
PARAMETERS (ug/kg)	IG-SS-01	IG-5B-04	IG-55-02	IG-SB-05	IG-SS-03	IG-58-06
BENZO(B AND/OR K)FLUORANTHENE	-			-		
BENZO-A-PYRENE	1103	-		-	1 -	†
DIMETHYLNAPHTHYLENE	-	-	-	-	†	400JN
ETHYLDIMETHYLAZULENE	-	1	-			800JN
METHYLPHENANTHRENE	-	-	<u> </u>		<u> </u>	-
METHYLPYRENE			_		 	+
METHYLTRIPHENYLENE	-	-				
BENZOPYRENE(NOT A)			1 -	-	<u> </u>	
METHYLANTHRACENE	•				<u> </u>	†
BENZOFLUORENE	-	-		-		†
BENZONAPHETHOTIOPHENE	-	-				
BENZOFLUORANTHENE	-		-			
DIBENZOCHRYSENE	-					
ONYLPHENOL	-	-	 			
ETRAMETHYLBUTYPHENOL	-			 		
DIETHYLETHANEDIYL)BISPHENOL	-					
ETROLEUM PRODUCT			N	N	N	+
UNIDENTIFIED COMPOUNDS/NO.	30001/3	 	20,0001/2	50001/4	40001/3	N 10,0001/6

Material analyzed for but not detected above minimum quantitation limit

J Estimated value

N Presumptive evidence of presence of material

SUMMARY OF ORGANIC ANALYTICAL RESULTS SEDIMENT SOIL SAMPLES ILLINOIS CENTRAL GULF RAILROAD LOUISVILLE, MISSISSIPM

	Background	Drainage Ditch			
PARAMETERS (ug/kg)	IG-5D-07	IG-SD-08	IG-SD-10	IG-5D-09	
PURGEABLE COMPOUNDS					
1,1-DICHLOROETHENE	-	-	-	-	
1,1-DICHLOROETHANE	-	-	-	-	
1,1,1-TRICHLOROETHANE	-		-		
TETRACHLOROETHENE	-		-		
TOLUENE	140	-	1 -		
TOTAL XYLENES	-	780J	1 -	-	
EXTRACTABLE COMPOUNDS				1	
NAPHTHALENE	2301				
-METHYLNAPHTHALENE	200)	4500J			
CENAPHTHYLENE	210J	-		†	
DIBENZOFURAN	130J		†	-	
PHENANTHRENE	120 0 J	3100J	2900J	1600)	
NTHRACENE	5001		-		
LUORANTHENE	ر7900		2700)	5000)	
YRENE	6900)	1700J	2400J	3900)	
ENZO(A)ANTHRACENE	4000)		520J	1500)	
HRYSENE	4300)		1200)	2500)	
ENZO(8 AND/OR K)FLUORANTHENE	56001		-		
ENZO-A-PYRENE	2200)	·	-		
METHYLNAPHTHYLENE	-			 	
THYLDIMETHYLAZULENE	-				
METHYLPHENANTHRENE	700JN		-		
1ETHYLPYRENE	800JN			 	
METHYLTRIPHENYLENE	400JN		-		
ENZOPYRENE(NOT A)	4000JN	•	•	 	
TETHYLANTHRACENE	600JN	-	-		
ENZOFLUORENE	1000JN		•		
ENZONAPHETHOTIOPHENE	400JN	·	-		
ENZOFLUORANTHENE	6000JN/2	-	•		
IBENZOCHRYSENE	20 00 JN/2	•	-	-	
ONYLPHENOL	-	10,000JN	-	-	
ETRAMETHYLBUTYPHENOL	-	1,000,000JN		5000JN	
DIETHYLETHANEDIYL)BISPHENOL	_	10000JN	-	9000JN/2	
ETROLEUM PRODUCT	N	N	N	N	
NIDENTIFIED COMPOUNDS/NO.	4000J/2	100,0001/8			

Material analyzed for but not detected above minimum quantitation limit Estimated value Presumptive evidence of presence of material

TABLE 6

SUMMARY OF INORGANIC ANALYTICAL RESULTS GROUNDWATER SAMPLES ILLINOIS CENTRAL GULF RAILROAD LOUISVILLE, MISSISSIPPI

PARAMETERS (ug/l)	IG-PW-11	
BARIUM	56	
CALCIUM	2800	
IRON	76,000	
MAGNESIUM	2100	
MANGANESE	140	
POTASSIUM	21001	
SODIUM	14,000	
ZINC	88	

Estimated value

The American Creosote Company was located adjacent to the site and was involved in the production of creosote. The presence of PNAs in the soil and sediment samples cannot be attributed to site practices due to the influence of the creosote plant and the railroad ties located on site. Several of the PNAs were detected in the background sediment soil sample, located upgradient of the NPDES discharge point, indicating the drainage path from the site is being influenced by offsite conditions.

Inorganic analysis showed lead to be above background values at two sampling locations. Lead was 5 times above background levels in one onsite surface soil sample. One drainage ditch sample contained elevated levels of lead and was located 5 feet downgradient of the NPDES discharge. The lead does not appear to be migrating off site since lead was not found at elevated levels downgradient in the ditch.

The inorganic analytical results of the municipal well sample are presented in Table 6. The levels of inorganic constituents present are not considered to be elevated. No organic parameters were detected at all in this sample.

5.0 SUMMARY

Analysis of soils collected from the site indicate the presence of chlorinated solvents, polynuclear aromatic hydrocarbons (PNAs) and the tentative presence of petroleum products. The chlorinated solvents are commonly used as degreasing agents and probably were deposited on the soil during the servicing of locomotives.

Although analysis of soils from the site shows the presence of PNAs, the PNAs cannot be attributed to site practices. PNAs are associated with coal-tar creosote used to preserve railroad ties. Since the Illinois Central Gulf Railroad service facility is located in a railroad yard, the presence of the PNAs may be attributed to the railroad crossties. Also, the American Creosote Company was formerly located next to the site and produced creosote. Background soil samples taken upgradient from the facility contain PNAs, indicating offsite conditions may be influencing the Illinois Central Gulf site. File material does not indicate that PNAs were ever produced, stored or deposited at the Illinois Central Gulf Railroad site. The petroleum products found in soil samples probably came from spills that occurred during the loading of diesel fuel and lubricants into locomotives. A diesel fuel tank and a lube oil tank are currently located on the property and are used to service locomotives. At the time of construction of the fueling and service center, several areas of soil contaminated with oil were removed. The presence of petroleum products in onsite soil samples can be attributed to site practices.

There are only two pathways of concern for the Illinois Central Gulf Railroad facility: the air and onsite exposure pathways. The groundwater is most likely not affected due to thick beds of clay separating the aquifer of concern from the areas of contamination. PNAs are relatively insoluble in water and are adsorbed onto particulate matter. Migration into the groundwater by PNAs is unlikely. The surface water pathway is not a concern due to a lack of potentially affected targets.

The presence of uncontained, contaminated surface soils was confirmed in this investigation and access to the site could be obtained by nearby residents. Additionally, the uncontained surface soils could be dispersed by the wind into nearby neighborhoods. However, only 411 people reside within 1 mile of the site.

Because the potentially affected population is small, migration of PNAs into groundwater unlikely and the aquifer of concern is protected by overlying beds of clay, FIT 4 recommends that no further remedial action be planned for the site.

REFERENCES

- NUS Corporation Field Logbook No. F4-1086 for Illinois Central Gulf Railroad, TDD No. F4-8809 Documentation of sampling investigation, October 11, 12 1988.
- 2. Charles H. Chisolm, Director, Bureau of Pollution Control, MS Department of Natural Resources. State of Mississippi Water Pollution Control Permit, National Pollutant Discharge Elimination System (NPDES), Permit No. MS0034762.
- 3. Kenny Morris, Louisville City Engineer, telephone conversation with Steve Cash, NUS Corporation, usage downgrade from Illinois Central Gulf Railroad.
- 4. T. Campbell, Engineering Department Blue Print, Oil Spillage Collection Facility, Illinois Central Gulf Railroad, DWG No. A-40349, File No. 182-81, December 9, 1977.
- Potential Hazardous Waste Site Preliminary Assessment (EPA Form 2070-12) and attachments for Illinois Central Gulf. Filed by Trey Fleming, Mississippi Bureau of Pollution Control, December 30, 1987.
- Joyce Kirkpatrick, City Clerk of Louisville, telephone conversation with Steve Cash, NUS Corporation, April 4, 1989. Subject: Population of Louisville.
- 7. U. S. Environmental Protection Agency, <u>Graphical Exposure Modeling System (GEMS) Data Base</u>, compiled from U.S. Bureau of the census data, 1980.
- 8. U. S. Department of Commerce, Climatic Atlas of the United States, (Washington, D.C.: GPO, June 1968) Reprint: 1983, National Oceanic and Atmospheric Administration.
- National Water Summary, 1984, Hydrologic Events, Selected Water-Quality Trends, and Ground-Water Resources, United States Geological Survey Water-Supply Paper 2275.
- L. A. Gandl, Characterization of Aquifers Designated as Potential Drinking-Water Sources in Mississippi, Water-Resources Investigations Open-File Report 81-550, 1982.

- 11. R. E. Taylor and F. H. Thompson, Water for Industrial Development in Kemper, Leake, Neshoba, Noxubee, and Winston Counties, Mississippi, Water Resources Division Study, USGS, 1972.
- 12. B. E. Wasson, Sources for Water Supplies in Mississippi, USGS, 1986.
- 13. Tommy Kirkpatrick, Louisville Utility System Manager, telephone conversation with Steve Cash, NUS Corporation, April 5, 1989. Subject: Municipal water usage in Louisville.
- 14. Tommy Kirkpatrick, Department of Public Works, City of Louisville, telephone conversation with Trey Fleming, Mississippi Bureau of Pollution Control, December 29, 1987. Subject: Municipal water usage in Louisville.
- 15. Endangered and Threatened Species, U.S. Fish and Wildlife Service, Region 4, Atlanta.
- Chemical, Physical, and Biological Properties of Compounds Present at Hazardous Waste Sites,
 U.S. Environmental Protection Agency, Prepared by: Clement Associates, Inc., September 27,
 1985.

&EPA

Potential Hazardous Waste Site

Site Inspection Report



Site Inspection Report

3EPA.	POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT PART 1 - SITE LOCATION AND INSPECTION INFORM	LIGENTFICATION OF TAIL 22 ST COMPA MS 000077356
A SITE HAME AND LOCATION		
III	ississippi M5 39379	CONTROL COMPANI
Same II	MANINE COSIC	Stot Hishuay 15
Louisville M.	iss. ssippi MS 39379	Winston 300
130646.0 0190		I C STATE I D COUNTY I E MUNICIPAL
IL MEPECTION INFORMATION		= 4 UNICHOWN
10 11 88 54	MACTING 1978 Press	±unacronn
A MARCY PROPERTY AND ACTION COME		
I A. SPA I/O SPA CONTRACTOR _ I E. STATE I P. STATE CONTRACTOR	Auto d'Ella	UNICIPAL CONTRACTOR
CONTRACTOR .		
Steve Cosh	Environmental Signat	X NUS 404938-771
offer sericions	10 mu	11 CHEMICATON 12 TRANSPORT OF
		(金)
		(4)
		()
		()
		()
Jorry Weaks Tim A. Leach	Field Eminerer	60/1949.43
T. 1	Troin- 1.0. Box	346 801-
im A. Leach	Moster Youisville	MS 39339 1773-87
		()
		()
		(1
, #		()
**		
0840	clear skys, tem	perstance 70°F
REPORTATION AVAILABLE PROME	3.757	
Trey Flening	MS. Byreau of loli	letion Could 1601961-517
Steve Cosh	NUS	404 935-7710 6 1 89
7000 3076 13 (741)	1143	4 30 / / U Sales 241 - 144

&E	PA .	PO	TENTIAL HAZI SITE INSPE PART 2 · WAS	1. 100 KT PICA	1. IDENTIFICATION 3. FIRE OF STREET AND THE PROPERTY OF THE P		
IL WASTE	STATES QUANTITIES, A	O CHARACTE					
51 MINSCA	STATES : "GO of the same of th	-	THY AT STE	CA TON	CTRAFFICE COME STATE OF THE STA	ABLE DE MON	TIME .
M. WASTE		-					
CATEGORY	NASTAICS N	-	01 09088 MICHAE	have a second			
SLU	SLUDGE		0.000	DI CHI CO CALLE	ST COLUMN		
OLW	OLY WASTE		UNK	 	+		
301	SOLVENTS		1120				
P90	PESTICIOES				+		
occ	OTHER ORGANIC CH	EMICALE			+		
œ	HOROMIC CHEMIC				+		
400	4C106				+		
146	\$48EB				+		
VES	HEAVY METALS						
V. HAZARO	OUS SUBSTANCES						
CATBOON	OR SUBSTANCE NA	-	04 CAS HARRIST	04 870Russ	SPORAL METHODS	06 CONCENTRATION	T BUILD AND
1209	Tetrachlow	ethq we	79-34-5	00		1900	-
1220	Talue~0		108-88-3	OL	,	560	uslis
1239	XVENES		1330-20-7			780	45/5
	Lead		7439-92-1	00		1300	45/75
	Phenanth			00		3/00	119/15
	Tetracthy	/-				3/00	45/FS
	Butuphen	0/					
PERDETO	313 B.31						
CATROON	1 manual						
F06			95 CAS PLANES	CAFFERMY	on Palatroan	Aud	OR CAS HUMBER
				700			
708				706			

SEPA

POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT

I. IDENTIFICATION

PART 3 - DESCRIPTR	ON OF HAZARDOUS CONDITIONS AND INCI	MS 0000	7739
IL HAZARDOUS CONDITIONS AND SICEOSITS			
31 Z A GROUNDWATER CONTAMBIATION 33 POPULATION POTENTIALLY APPECTED: ///	02 C COSSINED (DATE) SATTEMAL SA	LLEGED
31 I S SUAPACE WATER CONTAMINATION 33 POPULATION POTENTIALLY APPECTED.	02 = COMMENTED IDATE. 04 MARRATIVE DESCRIPTION	I POTENTIAL I A	ēGED
Air expisure poth	03 Commondate 10/11/97 04 HAMATIME DESCRIPTION	due to er-	
1 = 0. PREPLONG COLORIDA	contoninated so	offle site,	•
POPULATION POTENTIALLY APPECTED:	C4 RANGE CHECKSTON	S POTENTIAL 3 A	LEGICO
of uncontact possion pop	The all is of concern-		
5 441 :- 9 /	- Mile redius of	the site	
we site soils ove co	ontoninated with to Nuclear granatic	fractions of	60-0
POPULATION POTENTIALLY AND STATE OF A STATE	CO C COMPAND (BATE)	C POTENTAL 3 ALL	A940
NA	OR CI COMMING CONCRETE	C POTEMAL C ALL	.60ED
POPULATION POTESTIALLY APPETED.	OF INVENTION CONTROL	C POTENTAL C ALL	A940

SEPA

POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT

L DESTRICATION

PART 3-DESC	IMPTION OF HAZARGOUS CONDITIONS AND INCIDENTS	45 6	000773569
IL HAZARDOUS CONDITIONS AND INCIDE	NTS common		
01 TJ DAMAGE TO PLORA 04 NARRATIVE DESCRIPTION	02 C COMMED (DATE.	2 POTENTAL	= MLEGEO
	NIA		
31 T < DAMAGE "O FAUNA 34 NARRATIVE DESCRIPTION INTERPRETATION OF NAME		S POTENTIAL	I ALLEGED
01 II L CONTAMINATION OF FOOD CHAIN	NA		
04 NAMATIVE DESCRIPTION	N/A	I POTENTIAL	Calcala C
OI EN UNSTABLE CONTABBIENT OF WASTER		- POTENTIAL	I MLEGED
OS POPULATION POTENTIALLY APPECTED:	04 MARKATHE CESCRIPTION		र्स े ४
01 Z N DAMAGE TO OPPETE PROPERTY 04 NATRATIVE DESCRIPTION	N/A	POTENTIAL	S ALLEGES
01 CONTAMBATION OF SEWERS, STORM OF NAMEATIVE DESCRIPTION	N/A	POTEMAL	= ALEGED
01 T P CLEEN/UNINTHORIZED GLAFTIS 04 NATION CESCRITION		POTENTIAL	= ALEGED
ű.	NA		
ON CHECKSTON OF ANY OTHER HOUSE, POR	· n · / N		
.	·N/A		
L TOTAL POPULATED PRINCIPALLY APPL V. COMMENTS	7275		
. SOURCES OF REPORMATION do made week			
EPA and Star Inspection	Report.	5;/e	-

S EPA		ITE NEDEC	IS WASTE SITE TION PTIVE INFORMATION	OF THE DESTRUCTION OF STATE OF
IL PERMIT INFORMATION				11.000/7/30
OI TYPE OF PETRAT SELES	02 PERMIT NUMBER	OLON TIME	OF EMPERATION CATE OF COME	
	41	m/ 1-	1 (
TR NEGER	M50034762	9115783	6/30/99	
IC AM				
IO RORA				
TE RORA INTERNA STATUS	 			
23 STATE tour				
ZH LOCAL				
21 OTHER SHAPE	+			
TI YOM				
SITE DESCRIPTION				
	AMERICA DE LANT COLLA			
	AMOUNT OF WAT OF M	-	A Thereif allows at the same	DE GTH-GER
A SUFFACE MEQUIONERY			NC BORNATION	
C C OPLINE ABOVE GROUND		0 21	RESTRICTION SUSCION	THE HORSOMOLUS NE
C D. TANK, ABOVE GROUNG			DESCRIPTION.	1 3
	Zwk.		MOLOGICAL MATE OL PROCESSION	Ž Ž
ST WORL			CLYBIT RECOVERY	04 May 50 816
= 0. UNGFARM		- 34	THE RESTOLING RECOVER	. 1
= H. OPELOUMP			These	
CLOTHER			-	- 1
CONTAINMENT				
CONT APPROPRIOR OF WASTER ADDRESS OF	. /			
C A ADSCLATE SECURE	D. C. MARRIAGE	@ G. SWAGGOW	7E. POOR 0 B. RE	SOURCE UNICOUNCE, DANISONOUS
ACCESSEDATY SAFE				
OI WASTE SAGELY ADDRESSES. CI YES	Lid			
IOURCES OF IMPORES TION				
EPA a-d s Inspection	tala F; Report	les,	Scrooning	- 5:1a
GRM 3076-13 (7-61)				

			(18-1) \$1-0100 LINOT
			•
14.1.00 facility,	stabol -	2/1 × -4	prostin
200 to 10 10 10 10 10 10 10 10 10 10 10 10 10	OL STORIGOD +0	0945	Nogin
SOUTH AND THE MAN AND THE PROPERTY OF THE PROP	TEL S	MATHUM.	THE STATE OF THE PARTY AND ADDRESS OF THE PART
least -		HOWWINGS ALL	
7/. 7			
7/	7	2345 PT	DY B/1 61
STIR OT BOILVIEND GETOBRAN		7	5 0 4 > pff
		Spine to design (STORM TANKENDRECORPORATION SE
GREW Y CONSTITUTE CO D. NOT CURRENTLY USES	NOO 34 ATT SOURCE	MOTARM & D	OTANOS ADVISOR A D
			W. SUPLACE WATER
	CHD		ON 2
	SEAD I		EMBRACO PECTO
			Year Stamoby 6:
1-115 -1110	1005 -04	101 211	1104-200
Myonisoiddo 7 200	115 000 /1	חיכישפן הכ	דירם ממין
STATE STATE FOR SO	760	مراد	N-037
			AND AMOUND OF HT BO AO
The server money reserves of	BOWTEG CO	ODS Z	ALONO YS GRAMBE MOTALANON EC
SUBJECTION OF WORKERS AND	MOLYBOAN TYRUS	STATE STATES AND ADDRESS OF THE PERSON NAMED IN	
		/ .	TA ONLY SOURCE FOR GREEN
in the second se			RETAWONUORD MI
	50 DY	= 0 =	
ANOTHOR SET	DEVINENCE VALE	70M 2014	
376 OT SOMMED GO	SULLATE SO		A7445 040000 00 Bay 10
		A7	PRINCIPAL DISTRIBUTE A
THO THE ISLAND TO ATABLE DATA LATHERMORY	DENOGRAPHIC, AND EN	ASTAW - S TRAT	
STIE SITE AL INDIVIDUAL PROPERTY OF THE STIES ST	SITE INSPECTION REP		₩

POTENTIAL HAZARDOUS WASTE SITE

ÖEPA		FOI ENTIAL HA	AZARDOUS WASTE SITE	
~~~		AT E. WASTE SITE INS	PECTION REPORT	I. IOENTIFICATION
VA Change	- A	THE THE PER DEMOGR	PECTION REPORT IAPHIC, AND ENVIRONMENTAL DATA	AS 0000 773564
VI. ENVIRONMENTAL INFO	WOLT THEN		DATA	VIS 1000 773564
31 PRINCIPLITY OF . MALTINE	LED SOME CHANGE			
\$ 10-0.	- 10-4 cm/sec	C. 0. 10ns	☐ C. 10-4 10-3 envises ☐ O. GREATER	
		10" anress	□ C. 10-4 10-3 comme □ 0 comme	
32 PERMEABUTY OF BEDROCK	<b>1000 and</b>		C O CHAIR	THAN 10-3 envises
1				
.011	PERMEABLE	- E ATIVE Y MARRIED	TABLE IC RELATIVELY PERMEABLE IO	
NOORODE CT HTGGE EC			- O	VERY PERMEABLE
1	JA OEPTH	OF CONTAMENATED SON ZONE		Green was '0 ' I the same
1	1	2_	05 SCH, 4H	
36 VET PRECENTATION	-		11	
	07 ONE -E	M 34 HOLE RUSHER	104 5 200	
9.0	1	3.5	SITE SAME LONG TOWN OF SHEET	
DE PLOCO POTENTAL				TERRAIN AVERAGE SLOPE
		10	1003	
SITE SH YEAR	.0000	3 STE IS ON BAR	P. S. M. CO	
11 DETANCE TO WETLANDE I me me			RIGH IBLAND, COASTAL HIGH HAZARD AREA. RI	MERCE FLOCOWAY
ESTUARDO			12 Out Asset To Contract	
and the same of th		011460	12 CONTINUE TO CONTICAL MARTAT IN COMPANY OF	
I A	3-2-4			1
13 LANG USE IN VICINITY				
1			DOMESTED SPECIES	
CHETANCE TO:				
COMMERCIAL PROLETT	- P7 II	-	- design purposes services and the services	
- CONTROLLED		ACRESTE OF WELL	MALETATE PARKE	
1/2			OW DA DAM	TURAL LANCE
1 4-/2 -			2.35 2.66 - 5.55	~~~
				1
14 DESCRIPTION OF SITE OF ASSAULTED T	O Santistando	The state of the s		
1				
1				
1				
1				1
ł .				4
				10
li de la companya de				1
				1
1				1
I				f
I				j
ı				1
2				4
**				£
3				1
-				i
**************************************				ν.
				1
				1
TR. SOURCES OF BEFOREA THE				1
E N M	-			and the second s
EPA and	5-1-1	Fil		
- no	1791	e Files	Scroening Sile	
1~ spent:	0		Jeroen, -, 5:1	-
1001100	110	out	,	- 1
	0	, ,		1
PA PORMISST9-13(7-81)	1,500			1
				•

<b>∂EPA</b>		POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT PART 6 - SAMPLE AND FIELD INFORMATION	STATE COST STATE
A SAMPLES TAKEN			2000/1350
SAMPLE TYPE	SAMPLE TAND	01 SAMPLES 3847 10	
GROUNDWATER	1	0	SATE AVALAGE
SUPPACE WATER		E analysis	12/5/88
HASTE		ENVIRONMENTO/ Ma	-itoria
A.		Environmental Ma Services (EMSI)	3
NOT	+	L	
374	<del> </del>	Conbridge Analys	15-
308.	+	Conbridee Ana	dical
VEGETATION	10	As sociales a	12/2/20
	-		12/5/88
one			
THE MEASUREMENTS TO	AKEN   OR COMMAND		
PU	<del> </del>		
T			
lomp.			
Fox ductiv	2/ v		
MOTOGRAPHS AND MAPS			
THE ESTATE CHEST		Mariana NUS Corp.	
S-FEE SA LOSATES		Corp.	
OTHER PIELS BATA COLLEC		- W. P.	
:1			
	9		
	<b>.</b> 2		1
			į.
	•		
OVECES OF MESONA TION			ł
PA	< / /	AL AND AND AND	
7 9-4	state,	Files, Sereening	5:/e
		, ,	
rspectic.	- Mepo.	rt.	1

					libat breast mo
				-	- MOTTAMONE TO SECTION
-		APP	-	P. P. Berry	
3000 340 16		THE PARTY OF THE P	200.00		THE PERSON NAMED IN
1000018-41					<b>.</b>
					4
1000	وسطه		-	q-drue	
3000 300 140					
				***	<del></del>
3000 dg a	PLYAR M			مسعه	
3000 me re	5		-	1	
				1	
A3844 8+0 9		N. MEAL TY CONTRIBUTE A CONTRIBUTE OF THE PARTY OF THE PA		-4 30	
			<del> </del>		
3000 42 1	Jana Co		-	-	
3000 3411		100 100 TO 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
·			300 30 10	1	I THE THE PERSON LINES.
- SERVING SE	+			0 80	3000
-	DAY C.	401	-		
				TOWNAUS OF	
3000 348 11	T	Lan 1 Con. and 3 to \$20,000 to Table 101	3800 36 10	Ц	THE PART OF PERSON LEGISLE
490M/N 9+0 M		37M1 80	1000010-0	30	
\$000 et 1					,
2000	182428 6 1	MOEL	3000 4	10 ETATE 80	40.
3000 DE . 1		Lan. 4.0% and 0 4,6650000A TEMPTE OF	3800 38 10		
480mm 8+0 60		\$000 pt		]	
22. 2		2-114 50	NEWS SHOP	1 10	January 10
3000 gg + i	1844.6	410 21	2000 at	10 51478 00	4090
11 SE COOR		100 100 TO 0 0 0 000000 LINUS 01	3500 36 10		1 Marie 1887 - Marie 1987 - 1887
3780VTH 0+0 00					
		PARENT COMPANY Assessed	1887 N 9 +0	200	
12511000	1 CIP	NOTAMBONI R	MAD. / IMM.		A. CURRENT OWNERS.
179ELLOOD	STANSO	TACHEM MOITS	STARM BIRE		<b>₩</b>
MONAN	THE T	STIE STRAW BUOGN	ASAH JAITNET	04	407 O

<b>SEPA</b>	•		SITE INSPI	ARDOUS WASTE SITE ICTION REPORT ATOR REFORMATION	GI STATE IS	PICATION 21 STEINAGE 2006 7735
IL CURRENT OPERA	108 mirani			OPERATOR'S PARENT COMPAN		
OI MANN			OR D-G MANAGE	10 (000)		11 5-5 H.C.
OJ STREET ACCIDENCE . O	des APR de s		04 SE 0508	12 5 THE T ACCOUNTS 10 SEE 470 ME.		13 55 0003
os criv		GE STATE	07 29 COOM	14 617	15 STATE	10 th CODE
00 - CAND OF OFFICE POST	00 made of owner	)				
IL PREVIOUS OPERA	T08/2					
T NAME			04 0+ 6 HLAGES	PREVIOUS OPERATORS' PAREN	T COMPANIES .	11 0-6 Muladia R
S STREET ACCRESS IF O.						
			64 EC COM	12 STREET ASSESSED IN G. Co. 1997. CO.		13 SE COOR
6 CITY		<b>37/10</b>	N D COM	14 (319	HATEL	10 20 0000
YEARS OF OPERATION	S INC. OF CHARLES	LAG NA	7003			
True!		-		1745		; 11 6+8 H2 1881
START ASSESSED & C. D.	n. 1994, etc.		14 25 00 25	12 STREET ASSESSED F & SEA 4797 CO.		ì
				12 STREET ASSESSED P & Str. 494. CO.		13 85 600
CAV .				16 484	TERANE	10 20 0000
YEAR OF CHEMICAL	OF HAND OF GRAND	AUTO THE	163			
NAME .			F-I ILLER	10 Mag		11 0+614JA
-						
						13 05 0500
				14 (817)	10 00000	1900
THE STREET			<b>V</b>		L	
. soutces of ago						
•	·····································					
	<del>1</del>					
ORG 3870-13(7-61)						

					fig-gt to sale made van
					245
8		(25)			<b>f</b> .
				*	V. SOUNCES OF SUPPRISH THE COMME.
3800 es se					20
					400
3000 348 14	T		300 to 10	т	70 Year 10 9 4 600 100 100 100 100
188hazi 8-4 90	L	- India	30000		379410
1900 eg 18	BAYAS 00	A40 00	-		
				APPLY APPLY	440 90
3000 316 10		THE PARTY OF THE P	350 50 10	<del></del>	THE PART OF THE PROPERTY LABOUR TO
X80**** 0 +0 ±0		2000 10	1887710+4		<b>3700</b> : 10
Ì	7			T-1	M. Thaispointara
7000-410	TATE OF	4010	3004		AUD 90
3000 300 00			3000 per +e		1 0 mm to 41 00 00 00 00 00 12 00 12 00 00 00 00 00 00 00 00 00 00 00 00 00
A30000 8-0 10					
		5 m 10	1000010+0		3mm 10
1033 at 10	TATE BO	Ayi0 90	3000 45	0 STATE 00	A40 90
1000 DH +0		1900 F Gar 190 G d' SERVICE ARRALE DO	3000 30 10		1 200 1 200 140 0 4 BESTOON TSBOTTS CO
#300 T 8 - C 20		3994 LD	1 <b>60</b> 7701 9+0 3		
				1	(EMOTARBUSO STIR-RO JH
			\$000 gg /	0 21745 90	AID \$1
		j			
			3000 349 10	T	I ME NOW HE C. SEBROOM TENTE EC.
			100mm 9+02		<b>&gt;</b> 10
1955 LL 0000	I CW	HOIT AMINONIN RETROGENA	ATMOTARMED .	# TMAY	NOTAKBUBO BTIB-NO. JI
PICATION 52 STE TUNES	LNBO:	BTIS BTSAW SUOCH TROGEN HOIT:	SEASON BASE		<b>₩36</b>
			APAN IAITHETO		

AGREEV NO 34VG NO	OF GENERALICH COLLORS WITH
ACHERY 90 3490 80	SALD-COUNTY WOOD OF DE 10
ACRES SO 34VO SO NORMAN	NOU-MONEY TO
ACMESON SO NAVO SO	Mileson -
ACRESSES DO SONO DO	<b>**</b>
ASSESSA CO. Service Do.	MOLACINO 10
ACRESOV SO SERVO SO	ON CREATURE
ADMINIO DO SEMO DO	MOULENS TO 10
ASPEREN ED SENO BO	MOLLANDER TO 10
ADDESY SO SLIVE SO	MOLLEGOED PO
A2-68-Y 80 34-Y 80	
A3-68-V 50 34-VO 50	MOUNTED BEFORE TO TO
ACHIEROV ED BLVC ED	
Y2000A 80	GRADARY JOS GETAMMATNOS 3 C 10
ADMIN CC DS DVIE DS VOINCA	ON THE METAN THE MATTER SUPPLY PRO
ASMEDY CO	NOTITIES THE TANK WATER SUPPLY FRE
ACHEOV SO SLIVE SO	OD C A WATER SUPPLY CLOSED
SITE INSPECTION REPORT  PART 16 - PAST RESPONSE ACTIVITIES  A STEINING ACTIVITIES  A STEINI	ABITIVITIES AMONEM TEAS A
STIE STRAW SUOGRAZAH JAITHETON	<b>₩3</b> €

(19-2) EL GARE PROGRAM

-

3EPA	POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT PART 16 - PAST RESPONSE ACTIVITIES		MS 0000 77356
I PART RESPONSE ACTIVITIES -			
01 TR SANSET HALLS CONSTRUCTED 04 DESCRIPTION .	GE GATE	03 A44	
01 2 3 CAPPING COVERING 04 DESCRIPTION	02 DATE	03 AGENCY	
01 CT BULK TANKAGE REPAIRED 04 DESCRIPTION	OF DATE	OR AGENCY	
01 2 u GROUT CURTAN CONSTRUCTED 04 DESCRIPTION	OS DATE	03 AGENCY	
01 T V SOTTOM SEALED 04 DESCRIPTION	OS DATE	CO MEDICY	
O1 = W QAS CONTROL O4 OSSCRIPTION	OR DATE	06 AGDICY.	
O1 2 X FINE CONTROL 04 DESCRIPTION	of DATE	08 A6846Y	
OF THE STATE THE ATMENT	OF DATE	DE ARRECY.	f
01 2 2. AREA EMICUATED 04 DESCRIPTION		OR ARRICY.	
01 2 1 ACCESS TO SITE RESTRICTED 04 DESCRIPTION	06 GARS	CO MEDICY.	
01 C 2. POPLIATION RELOCATED 04 DESCRIPTION	34 BASE	OS ASSEST	
OT C 2. OTHER PENEDAL ACTIVITIES OF CHECKET PRODU	4 to 1	19 A48401	
*	5		
SOURCES OF REFORMATION AND ADDRESS.			
OF 1876 13(7-41)			



POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT PART 11 - ENFORCEMENT INFORMATION

L OBSTIFICATION
M3 2000 77 3564

-		
•	EMPORCEMENT	A TOTAL OF THE PARTY OF THE PAR

- OI PAST REGULATORY ENFORCEMENT ACTION 2 YES 2 NO
- SE DESCRIPTION OF PEDERAL STATE, LOCAL PEDEATOR/PEPORCEMENT ACTION

S. SOURCES OF REPORTATION AND ADDRESS OF MARK AND ADDRESS OF THE PARTY OF THE PARTY